

3626 Dei Amo Boulevard, Surie 180 Terrance, Carriornia 96803-1643 (310) 370-8370 (310) 370-7038 PAK www.hygieneloch com

May 8, 2008

State of California Board of Equalization 450 N Street Sacramento, California 94279

Document No. 20805001.1

Attention:

David Gau

Regarding:

Review of Mitigation and Clean Up Procedures for Interior Electrical/Data Rooms,

Janitorial Rooms, Supply Rooms, Copy Rooms, Storage Rooms, and Rest Room Areas

Dear Mr. Gau:

Today, Hygiene Technologies International, Inc. (HygieneTech) received a copy of the "Mitigation and Clean Up Procedures for Interior Electrical/Data Rooms, Janitorial Rooms, Supply Rooms, Copy Rooms, Storage Rooms, and Rest Room Areas" prepared by BioMax Environmental, LLC dated May 7, 2008. Upon review of said document, HygieneTech concurs with the recommendations and has no additional comments or questions at this time.

If you have any comments or questions, please fell free to contact our offices directly at (310) 370-8370.

Sincerely,

HYGIENE TECHNOLOGIES INTERNATIONAL, INC.

Kenny K. Hsi, CIH Technical Director